



ABN: 60 341 526 043 18 Stacer Street Upper Coomera, QLD 4209 Mob: 0410 657 399 email: <u>info@slipsmartaustralia.com.au</u>

This report has been prepared for: *MJS Floorcoverings Pty. Ltd.*

35 Dividend Street , Mansfield QLD 4122

Test Site: Laboratory Tests Tru Plank Cushion – Hardwood Manhattan Report Number: W1130 Date Tested: 02/02/2022 Australian Standard Applied: AS4586:2013 Nature and Purpose Of Tests: The Nature of the Wet slip tests is as per AS4586:2013 Appendix A

The purpose of the Wet slip test is to ascertain an SRV for the surfaces requested.





18 Stacer Street Upper Coomera QLD 4209 email: <u>info@slipsmartaustralia.com.au</u>

Mob: 0410 657 399

WET Slip Resistance Test Report for Pedestrian Surfaces

This report has been prepared for: *MJS Floorcoverings Pty. Ltd.*- Kerry Krebs,

35 Dividend Street , Mansfield QLD 4122

Tes	t Site: Laborato		Plank	Cush	ion – Hardwood I	Manhattan 4mm/0	.55 x 228	x 1524n	nm*		
Standard Applied:	AS 4586 -2013	Notes: 1. The areas tested below were carried out on site using the Wessex Pendulum friction tester ID: SK1271, conditioned with grade P400 paper followed by wet 2 misron lapping film to evaluate the frictional observatoristics of the pedestrian surface.									
Rubber Type:	Slider 96	 wet 3 micron lapping film, to evaluate the frictional characteristics of the pedestrian surface. 2. SlipSmart Pty Ltd assumes no responsibility or civil liability for any actions whatsoever that may arise as a result of the tests and the publication and issue of this test report. 3. Slip test results always remain the property of SlipSmart Pty Ltd. This test report is intended for viewing solely for the named recipient identified above. 4. This report contains privileged and confidential information. The unauthorised reproduction of this report is prohibited. 									
Fixed or unfixed surface:	Unfixed										
Cleaning type:	Nil										
Topography:	Lab	5. While SlipSmart Pty Ltd takes care in preparing the reports it provides to clients, it does not warrant that the information in this particular report will be free of errors or omissions or that it will be suitable for the client's purposes.									
Accelerated wear (if appropriate):	n/a	Environmental Conditions:			Overcast			Date tested:		02/02/2022	
Slope:	n/a	Temperature	e:	25°C			Job	Job Number: W1130			
Sample Tested			Air Temp. °C		Floor Type	Coating	British Pendulum Number	Slip Resistance Value	Slope Correction Value	Equivalent AS4586-2013 Classification	
Test area #1			25	4mm/0.	55x228x1524mm vinyl	Nil	45				
Test area #2 Test area #3 Test area #4 Test area #5			25	5 4mm/0.55x228x1524mm vinyl Nil 44							
			25	4mm/0.	55x228x1524mm vinyl	Nil	43	43	00	P3	
			25	4mm/0.	4mm/0.55x228x1524mm vinyl Nil 39						
			25	4mm/0.	55x228x1524mm vinyl	Nil	42				

Other observations:

Remarks: *Sample details supplied by Client

Signatory **Brent Vournechis**

Peter Vournechis

Tested By: B Vournechis





18 Stacer Street Upper Coomera QLD 4209 email: <u>info@slipsmartaustralia.com.au</u> Mob: 0410 657 399

